

SITE NAME : AUSTIN & LIGHT COMPANY
SITE LOCATION: AUSTIN
SITE NUMBER : TXD987989357
FILE LOG # : 410

ROUTE SLIP
HAZARDOUS WASTE SITE - INSPECTION REPORT

	INITIALS	DATE	TIME (HOURS)
1. JOHN ELLIS	JP	3/11/91	0.5
2. WARREN NORRIS	WN	3/11/91	—
3. HERB DAVIS (Cover memo, Xerox copies of report, log out of file, file) (Copies to Hickam, Wright 6H-ES)	HD	3/12/91	.3

FILE CODE: SFD-24-1-5

1.8

BOOK REGISTER LOG #: 1395

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : AUSTIN GASLIGHT COMPANY
LOCATION : AUSTIN
SITE NUMBER: TXD987989357
SURVEY DATE: 8/24/90 INSPECTED BY: STATE FIT TAT OTHER: _____
LABORATORY : CLP EPA OTHER _____
RECEIVED FROM: ED SHERRA DATE RECEIVED: 1/31/91

SAMPLE TYPE(s):

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>N</u> Keep Site Active ("N"-No Further Action)
	<u>N/A</u> Concur with Report Recommendations

SUMMARY:

This is the information gathered on an off-site reconnaissance of the Austin Gaslight Company site in Austin, Texas. The attached memorandum states that there are no visible signs of the defunct company's coal gasification plant. A high rise office now occupies the site. For this reason, no preliminary assessment was conducted.

RECOMMENDATIONS:

We have no comment on this site at this time.

Concurrence:

F. W. Over News 3/11/91

J. P. Ellis 3/11/91
ENGINEER/REVIEWER